


Place SAM 01 profile block on side spindle 2.
 Place SAM 01 profile block on side spindle 3.
 Place Adjustable Groover on the first top spindle, to produce Groove.

Please tick in box - Is groove a visible top surface for priming YES NO



PRINTED COPY UNCONTROLLED

CUSTOMER TO CONFIRM DIMENSIONS A+B+C INCLUDING PRODUCT WIDTH AND THICKNESS

<p>SAM MOULDINGS Newpark Industrial Estate Greystone Road Antrim BT41 2RU Tel : (028) 9442 8288 Fax : (028) 9442 8244 Website: www.sammouldings.co.uk Email: info@sammouldings.co.uk</p>	PROFILE	DRAWN BY	M.KIRKPATRICK	REV:
	SP 600	DATE	23/5/00	AUTH:
		SCALE	1:1	TOLERANCE +/- 0.5MM