

└ TRANSPORT & STORAGE GUIDE

Prior to installation, Knauf Danoline ceiling and wall lining products must be stored clean and dry, between 0°C and 50°C, and with a relative humidity not exceeding 70% RH, and not subject to any abnormal conditions

TRANSPORTATION

It is recommended when transporting and storing Knauf Danoline products that they must be:

- positioned on a level base
- stored indoors
- protected from direct moisture
- protected from impact and shock
- opened carefully without damaging the products
- stored at humidities of less than 70% RH
- stored at temperatures of less than 50°C

When transporting Knauf Danoline products, it is recommended not to stack more than 2 pallets on top of each other.

STORAGE

When storing Knauf Danoline products, it is recommended not to stack more than 3 pallets on top of each other.

