

cetus

Inspired Perspectives

heavy contract  
6 colourways





Denab 8010  
(LRV - L34.22 Y8.25)



Menkar 8020  
(LRV - L21.57 Y3.44)



Mira 8030  
(LRV - L22.60 Y3.72)



Schemali 8040  
(LRV - L16.78 Y2.26)



Collum 8050  
(LRV - L15.41 Y2.00)



Rana 8060  
(LRV - L19.84 Y3.07)



|                     |                     |
|---------------------|---------------------|
| <b>Product Name</b> | Cetus               |
| <b>Yarn Type</b>    | Universal Nylon 6.6 |
| <b>Dye Yarn</b>     | Solution Dyed       |
| <b>Construction</b> | Hi / Lo Loop        |
| <b>Pile Height</b>  | 5.0 / 3.0mm         |
| <b>Tile Size</b>    | 500mm x 500mm       |

|                            |  |
|----------------------------|--|
| <b>Flammability</b>        | Cfl-S1   |
| <b>Anti-static</b>         | Less than 2kV Suitable for use in computer rooms |
| <b>Standard Backing</b>    | Bitumen  |
| <b>Wear Classification</b> | Heavy Contract                                   |

**INSTALLATION**






Sub floors should be clean, dry and flat and prepared in accordance with BS5325. Timber floors should be covered with plywood or other appropriate sheet materials. For tiles use F Ball tackifier F41 or Laybond 79. Tiles may be laid tessellated or broadloom. Tiles should be allowed to condition for a minimum of 24 hours at the expected temperature and humidity prevailing when the building is in use. Further installation information is available from the Paragon Sales Office.

**COLOUR**

For technical reasons, as with all textile materials, it may not be possible to colour match from different batches. Orders requiring colour match should be placed at the same time. Production may therefore show variations to the sample card.

**MAINTENANCE**

It is recommended that a maintenance schedule be initiated from the date of installation to achieve maximum life expectancy of the product. Regular vacuum cleaning with a twin motored upright vacuum cleaner is essential. All spillages and stains should be attended to immediately. For detailed information, please consult the Paragon cleaning and maintenance guide. It is imperative that all internal carpets are well protected from outside soiling and moisture by the use of barrier matting such as MatWorks, also available from Paragon.

|   |   |  |   |   |
|---|---|--|---|---|
| <br>545333<br>13 | <br>Certificate No EMS12345<br>Fully accredited with EC14601 | <br>F480644<br>BS EN ISO 9001 |  |  |
|   |   |  |   |   |

# paragon

CARPETS

Farfield Park  
Manvers  
Wath-upon-Dearne  
Rotherham, S63 5DB.

T. +44 (0) 1709 763 839  
F. +44 (0) 1709 763 813  
E. [sales@paragon-carpets.co.uk](mailto:sales@paragon-carpets.co.uk)  
W. [www.paragon-carpets.co.uk](http://www.paragon-carpets.co.uk)

